

## Airworthiness Directives; Engine Alliance Engines

---

Published October 8, 2026

District of Columbia statewide, DC - District of Columbia statewide County, DC

<https://noticenearby.com/notices/ingest-1ed393243e4818e5>

### Airworthiness Directives; Engine Alliance Engines

The FAA is adopting a new airworthiness directive (AD) for certain Engine Alliance (EA) Model GP7270, GP7272, and GP7277 engines. This AD was prompted by a report of an aborted takeoff that resulted from an uncontained failure of the high-pressure turbine (HPT) interstage seal. This AD requires removal from service and replacement of the HPT interstage seal with a part eligible for installation. The FAA is issuing this AD to address the unsafe condition on these products.

Agency: Transportation Department, Federal Aviation Administration.

Document type: Rule.

Document number: 2026-20666.

Official Federal Register document. Matter furnished by the National Archives Federal Register API. Notice Nearby is not the publisher of record for this item.

Source:

<https://www.federalregister.gov/documents/2026/10/08/2026-20666/airworthiness-directives-engine-alliance-engines>