

Airworthiness Directives; The Boeing Company Airplanes

Published September 17, 2026

District of Columbia statewide, DC - District of Columbia statewide County, DC

<https://noticenearby.com/notices/ingest-547d0d0d3ed2c199>

Airworthiness Directives; The Boeing Company Airplanes

The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-8, 737-9, and 737-8200 airplanes. This AD was prompted by reports indicating cracks in the bear strap and stub frame at the forward galley door cutout. This AD requires inspections for existing repairs; an inspection for any crack of the fuselage skin, bear strap, and stub frame; repetitive inspections for any crack of the bear strap and stub frame; and applicable on-condition actions. The FAA is issuing this AD to address the unsafe condition on these products.

Agency: Transportation Department, Federal Aviation Administration.

Document type: Rule.

Document number: 2026-19082.

Official Federal Register document. Matter furnished by the National Archives Federal Register API. Notice Nearby is not the publisher of record for this item.

Source:

<https://www.federalregister.gov/documents/2026/09/17/2026-19082/airworthiness-directives-the-boeing-company-airplanes>